



# EXIT AT THE STEEL STACK TOP


Top plate



ventilation gap



Hinge of stainless steel



handle

Rev. 01-08-2012